
















TWO-WAY RADIO CABLE COMPATIBILITY LIST FOR SM1P & SM1B

DOC00082 AA.02 (Draft)		MODEL	SENSEAR PART NUMBER	Revision
CONNECTOR PICTURE	MANUFACTURER			
 <p>MOTOROLA XTS, MTS</p>	MOTOROLA	XTS1500, XTS2500, MT2000 , MTX838 , MTX8000 , XTS2250, XTS3000Astro, XTS5000, MT1500, MTS1500, GP900, GP9000, HT1000 , JT1000, MTS2000, MTX9000 , MTX-LS , XTS3500, XTS3000, PR1500	SRCK6108	AA.01
	EF JOHNSON	51SL , 5000 series, 5100 series, 7700 series, Multi-net Ascend		
 <p>KENWOOD MULTIPIN</p>	KENWOOD	NexEdge NX210, NexEdge NX5300, TK-3140, NexEdge NX200/300, NexEdge NX410, TK-280, TK285N, TK-290, TK-480, TK-2140, TK-3180, TK-190, TK-380, TK-385, TK-390, TK-481, TK-2041, TK-2180, TK-3148, TK-5210, TK-5310, TK-5220, TK-390, TK-5400, TK-5320, TK-5410, TK-5310	SRCK6111	AA.02
 <p>MOTOROLA MOTOTRBO</p>	MOTOROLA	XPR 6000 Series (XPR6100 , XPR6350, XPR6380 , XPR6550, XPR6580 , XPR6500, XPR6300), XPR 7000 Series (XPR7550, XPR7350, XPR7580 , XPR7380), DP3000 Series (DP3400, DP3401, DP3600, DP3601), DP4000 Series (DP4400 , DP4401, DP4600 , DP4601 , DP4800 , DP4801), DGP 4150, DGP4150+, DGP6150, DGP6150+, DGP8050/5050, DGP8550/5550, XiR P8200, XiR P8208, XiR P8260, XiR P8268, XiR P8600 , XiR P8608, XiR P8620 , XiR P8628 , XiR P8660 , XiR P8668, GP328D , GP338D , MTP6550, MTP850S, MTP6750, MTP830S	SRCK6114	AA.03
 <p>KENWOOD 2-PIN</p>	HYT	TC265 , TC266 , TC268 , TC368 , TC620 , TC700EX	SRCK6113	AA.02
	KENWOOD	TK-3202, TK-360, TK-3170, TK-3207, TK-3303, TH-D7, TH-D7A, TH-D7AG, TH-D7E, TH-F6, TH-F6A, TH-F7, TH-F7E, TH-G71, TH-G71A, TH-G71E, TH-K2, TH-K2A, TH-K2AT, TH-K2E, TH-K2ET, TH-21, TH-21AT, TH-21BT, TH-22, TH-22A, TH-22AT, TH-22E, TH-25, TH-26, TH-27, TH-28, TH-28A, TH-31AT, TH-31BT, TH-41AT, TH-41BT, TH-42, TH-42A, TH-42AT, TH-42E, TH-45, TH-46, TH-47, TH-48, TH-48A, TH-55, TH-75, TH-77, TH-77A, TH-78A, TH-G71, TH-205, TH-225, TH-235, TH-235A, TH-235E, TH-315, TH-415, TK-208, TK-220, TK-240, TK-240D, TK-248, TK-250, TK-260, TK-260G, TK-270, TK-270G, TK-272G, TK-373G, TK-308, TK-320, TK-340, TK-340D, TK-348, TK-350, TK-353, TK-360G, TK-370, TK-370G, TK-372G, TK-373, TK-430, TK-431, TK-2130, TK-2160, TK-2170, TK-2200, TK-2207, TK-3130, TK-3160, TK-3173, TK-3200, TK-3201, TK-278G/378G/388G(Pro Talk), TK-2100/3100(Pro Talk), TK-2102/3102(Pro Power), TK-2107/3107(Pro Talk), TK-3101/3131(Free Talk), TK-2130/3130/3131(Pro Talk XLS), TK-3101(Free Talk XL), TK-2212, TK-2202, TK-2300, TK-2360, TK-3212, TK-3230, TK-3230XLS, TK-3350, TK-3360, TK-072A, TK-3300, TK-170, TK-2302, TK-3302, TK-2312, TK-3312, NexEdge NX220, NexEdge NX320, TK-2307, TK-3307		
	RELM / BENDIX KING	RPU416 , RPV516 , RPU499 , RPV599X , RPV516A , RPV599A Plus , RPU416A , RPU499A Plus , RPU4200		
	UBZ	LF48		
 <p>Motorola Mototrbo Slim</p>	MOTOROLA	DP2000 Series (DP2400, DP2600), XPR3000 Series (XPR3300, XPR3500), DP3441 , XiR P6600, XiR P6620 , XiR E8608 , XiR E8600 , DEP550, DEP570 , DGP8050 ELITE, MTP3100, MTP3250, XiR E8600, XiR E8606,	SRCK6166	AA.02



TWO-WAY RADIO CABLE COMPATIBILITY LIST FOR SM1P & SM1B

DOC00082 AA.02 (Draft)		MODEL	SENSEAR PART NUMBER	Revision
CONNECTOR PICTURE	MANUFACTURER			
 <p>MOTOROLA 2-PIN</p>	BEARCOM	BC120, BC130	SRCK6109	AB.01
	TEKK	XU100, XV100, XU1000, XV1000		
	RELM / BENDIX KING	RP6500		
	BLACKBOX	V, H		
	HYT	TC610, TC620, TC700, TC1600, TC500, TC508, TC518, TC600, TC626, TC580, TC446S, POWER446, TC2100, HYT2100, Titan, TR200, TR400, PD40x, PD50x, PD56x		
MOTOROLA	CP200, SP50, MAGONE/BPR40, RDU2020, RDU4100, RDU4160, RDU4160-D, CP040, GP300, DTR650, EP450, GP3688, CP88, ECP100, CP100, CP125, CP150, CT150, CT250, CT450, CT450LS, GP68, GP88, GP88S, GP280, GP308, GP320, GP350 (requires Motorola adapter HLN9482), GP1280, GP2000, GTI, GTX, LTS2000, P040, P080, P110, P200, P1225, P1225LS, PR400, PRO1150, PRO2150, PRO3150, SP10, SP21, VL50, VL130, XTN445, XTN446, XTN500, XTN600, XU1100, XU2100, XU2600, XV1100, XV2100, XV2600, CLS Series, PMR446, Spirit MU-11C, MU-21CV, MU-22CVS, MU-24CVS, MV-11C, MV-21CV, MV-21CVS, MV-24CVS, XTN446, XTN500, XTN600, VL50, VL130, DTR Series, P1215, BC90, CP185, BC10, BC95, RDX Series, RDU Series, RDV Series, GP3188, CP200d, DP1400, XiR P3688, DEP450			
 <p>ICOM 2-PIN</p>	COBRA	ALL TWO PIN	SRCK6112	AB.01
	ICOM	IC-41W, IC-F4023S, IC-F43GS, IC-40S, IC-F3G, IC-F3GS, IC-F4G, IC-F4GS, IC-3S, IC-40GX, IC-4008, IC-4088A, IC-F3, IC-F4, IC-F4S, IC-F10, IC-F11, IC-F11S, IC-F14, IC-F14S, IC-F15, IC-F20, IC-F21, IC-F21S, IC-F22, IC-F24, IC-F24S, IC-F30G, IC-F31, IC-F33, IC-F33G, IC-F43G, IC-F43TR, IC-F3001, IC-F3011, IC-F3021, IC-F3021S, IC-F3021T, IC-F4001, IC-F4011, IC-F4021, IC-F4021S, IC-F4021T, IC-F4101, IC-F4041, IC-F3101, IC-F3041, ICF3061, IC-F40, IC-F40S, IC-F4TR, IC-H2, IC-H6, IC-J12, IC-M5, IC-U12, IC-U16, BC100, IC-F3033, IC-F4033, IC-41S		
	MAXON	PL1145, PL2215, PL2245, PL2415, PL2445, SL25, SL55, SP100, SP120, SP130, SP140		
	MOTOROLA	Distance, Distance DPS, Talkabout 200, Talkabout 250		
	RITRON	Jobcom JMX, Jobcom MBX, Patriot Series RTX, Patriot Series SST		
	UNIDEN	UH040, UH042, UH044, UH050, UH052, UH056		
	VERTEX	VX200, VX500, VX510, VX520UD		
 <p>Vertex Single Pin</p>	VERTEX	VX427, EVX539, VX456, VX231, VX351, VX130, VX160, VX180, VX210, VX210A, VX400, VX410, VX420, VX354, VX451, VX454, VX459, VX230, VX350, VX450, VX426	SRCK6127	AA.02
 <p>Hytera 2-pin with locking screw</p>	HYT	PD502, TC-700, TC-610, TC-618, TC-620, TC-626, TC-518, TC-580, TC-446S, TC-508, POWER446	SRCK6299	AA.01
 <p>GME 2-Pin</p>	GME	TX675, TX6100, TX6000, TX6200, TX7000	SRCK6121	AA.01
 <p>MOTOROLA GP328 PLUS</p>	HYT / HYTERA	TC610P, TC780, TC3000, TC3600, SIMILO9180, TC700P	SRCK6106	AA.01
	MOTOROLA	GP328Plus, EX500, EX600, GL2000, GP338Plus, GP344, GP388, PRO5150elite, EXS560XLS, GP628Plus		
	SIMOCO	SRP9180		
	RELM / BENDIX KING	RPV3000, RPV3600, RPU3000, PRU3600, 3300C, RPV7500		

TWO-WAY RADIO CABLE COMPATIBILITY LIST FOR SM1P & SM1B

DOC00082 AA.02 (Draft)		MODEL	SENSEAR PART NUMBER	
CONNECTOR PICTURE	MANUFACTURER			Revision
MOTOROLA GP328 	MOTOROLA	GP328, GP329, GP338, PTX760, MTX960, MTX850, MTX850LS, PRO5150, PRO7550, ATS2500, PR860, HT1250LS+, MTP700, GP1280, GP140, GP320, GP339, GP340, GP360, GP380, GP640, GP650, GP680, HT1250, HT1250LS, HT1550, HT1550XLS, HT750, MTX8250, MTX8250LS, MTX9250, MTX950, PRO5350, PRO5450, PRO5550, PRO5750, PRO7150, PRO7350, PRO7450, PRO9150, PTX700, PTX780, MTX950, MTX900, PRO7750, MTP850Ex, MTP810Ex	SRCK6107	AA.01
ICOM 14-Pin 	ICOM	IC-F3261, IC-F3262, IC-F4261, IC-F4262	SRCK6105	AA.01
ICOM MULTIPIN 	ICOM	IC-F60, IC-F4163S, IC-F50, IC-F51, IC-F61, IC-F30G, IC-F30GT, ICF-30GS, IC-F31GS, IC-F31GT, IC-F40G, IC-F40GS, IC-F40GT, F70, F80, M87/88, IC-F3061 Series, IC-F4061 Series, IC-F3161 Series, IC-F4161 Series, IC-F31, IC-F41G, IC-F50V, IC-F60V	SRCK6110	AA.01
VERTEX MULTIPIN 	VERTEX	VX821, VX820, VX824, VX829, VX920, VX921, VX924, VX929, VX871, VX874, VX879, VX971, VX974, VX979, VXD720, VTX720	SRCK6117	AA.01
TAIT TP8110 	TAIT	TP8110, TP8115, TP8120, TP8135, TP8140	SRCK6148	AA.01
Hytera PD78X 	Hytera	PD78X, PD70X, PD70XG, PD78XG, PD88XT, PT580, PT580H, PD75X	SRCK6165	AA.01
Hytera X1e 	Hytera	PD60X, PD66X, PD68X, X1, X1e	SRCK6184	AA.01

TWO-WAY RADIO CABLE COMPATIBILITY LIST FOR SM1P & SM1B

DOC00082 AA.02 (Draft)		MODEL	SENSEAR PART NUMBER	Revision
CONNECTOR PICTURE	MANUFACTURER			
Sensear SR External PTT 	SENSEAR	SM1P	SRCK6170	AA.01
SM1P Flying Leads Normal Length Without Inline PTT 	SENSEAR	SM1P	SRCK6168	AA.01

PS:	<p>1. Cables in BLUE have been partially system tested.</p>
	<p>2. All SM1P & SM1B SRCK61XX Cables include Inline PTT.</p> 
	<p>3. All SM1P & SM1B SRCK62XX Cables do not have inline PTT.</p>
	<p>4. Cables in RED will be available end of Oct 2017.</p>