

Calibrating your IAQ-MAX Step-by-Step Procedure:

Step 1) Enter the “Settings” menu for the device by pressing the middle power button located on the back of the device, 2 times.

Step 2) Scroll down through the settings by using the power button until you reach “CAL”.

Step 3) Press either arrow button to toggle the CAL feature “OFF”.

Step 4) Continue scrolling through the complete settings menu. You must scroll through the entire menu for the settings to save.

Step 5) Take your IAQ-MAX outside and leave it outside, by itself for 5 minutes.

Step 6) Do not breath on or near your device as the CO2 from your breath will affect the calibration – Stay at least 6 feet away from the device while it calibrates.

Step 7) Hold the device so that the color display is facing you. Using your right-hand reach around to the back of the device and find the right-hand arrow button. You will need to use this button for step #8.

Step 8) Press and hold the right-hand arrow button while the device is facing you, until the device beeps once (could be up to 15 seconds). Then release the button. The beeping indicates that the device is about to begin its calibration procedure.

Step 9) Set the device down outside and walk away. Do not approach the device for at least 10 minutes.

Step 10) When you return after the 10-minute period the device should be calibrated. Depending on the outdoor air quality in your area the device will likely read between 400-450 ppm.

****Please note, do not place your IAQ-MAX in direct sunlight, doing so will negatively affect the overall calibration and operation of the device. ****